


Recommended Tools For Flashpoint Equipment



- | | |
|-------------------------------------|--|
| 1. Screw driver(PH x 80) | 10. Sand paper |
| 2. Screw driver(2.5 x 0.4 x 75) | 11. Bras brush |
| 3. Allen key (SW 3.0mm) | 12. Pliers |
| 4. Setting gage (0.05 mm – 1.00 mm) | 13. Syringe (10 ml) + PVC tube 6/4 (50 mm) |
| 5. Tool for pressure calibration | 14. Allen key (SW 2.5mm) |
| 6. Allen key (SW 1.5mm) | 15. Screw driver(512 PHILLIPS 2) |
| 7. Allen key (SW 1.2mm) | 16. Silicon grease |
| 8. Wheel stand | 17. Two component glue (Araldite) |
| 9. Distance gage | |